

Install Guide

- 1. Turn off/uninstall antivirus software
- 2. Plug the USB Display dongle
- 3. Run the driver setup software in USB Mass Storage Device

OS	Driver
Windows	xx.exe
MacOS	xx.dmg
Android	xx.apk

- 4. Reboot the system

Drivers Download

USB Display Driver For Win7 / Win8 / WinVista / Win10 / Win11

Latest Release

[MSDisplay_MultiDev_v1.0.0.18.0.exe](#)

Older releases

[MSDisplay_MultiDev_v1.0.1.60.exe](#)

[MSDisplay_MultiDev_v1.0.1.4.exe](#)

[MSDisplay_MultiDev_v1.0.1.3.exe](#)

USB Display Driver For WinXP

Latest Release

[MSDisplay_v1.0.0.0_XP.exe](#)

Older releases

USB Display Driver For MacOS

Latest Release

[MSDisplay_MacOS_v1.0.2b_20201125.dmg](#)

Older releases

[MSDisplay_MacOS_v1.0.2_20200926.dmg](#)

[MSDisplay_MacOS_v1.0.1.0_20200309.dmg](#)

USB Display Driver For Android

Latest Release

[MSDisplay_Android_v2.0.0.3.apk](#)

Older releases

MS9120_V1.0.1.6_release.apk

FAQ

1. The driver was killed by antivirus software

- Add the file into the antivirus software 'Exceptions' or 'Trust' list

2. Is it support Win7?

- Need Win7 SP1 or above

3. Black screen with mouse only with MacOS?

- System Preferences -> Security & Privacy -> Privacy -> Screen Recording, find screen_capture_msdisplay and check that

4. Portrait mode doesn't work on Windows?

- Can not support